DTC P2A00 A/F Sensor Circuit Slow Response (Bank 1 Sensor 1)

CIRCUIT DESCRIPTION

Refer to DTC P2195 and P2196 on page DI-421.

DTC No.	DTC Detection Condition	Trouble Area
P2A00	 In condition (a), (b) and (c), when the A/F sensor output voltage change value is below the regular value against the fuel trim change value, the ECM judges that A/F sensor circuit has slow response: (2 trip detection logic) (a) After engine is warmed up (b) During vehicle driving at engine speed 1,400 rpm or more (c) Vehicle speed 60 km/h (38 mph) or more 	 Open or short in A/F sensor circuit A/F sensor A/F sensor heater EFI main relay Air induction system Fuel pressure Injector ECM

WIRING DIAGRAM

Refer to DTC P0134 on page DI-278.

INSPECTION PROCEDURE

HINT:

Hand-held tester only:

The narrowing down the trouble area is possible by performing ACTIVE TEST of the following "A/F CON-TROL" (A/F sensor, heated oxygen sensor or another can be distinguished).

Perform ACTIVE TEST by hand-held tester (A/F CONTROL).

HINT:

"A/F CONTROL" is an ACTIVE TEST which change the injection volume to -12.5 % or +25 %.

- (1) Connect the hand-held tester to the DLC3 on the vehicle.
- (2) Turn the ignition switch ON.
- (3) Warm up the engine with the engine speed at 2,500 rpm for approx. 90 sec.
- (4) Select the item "DIAGNOSIS/ENHANCED OBD II/ACTIVE TEST/ A/F CONTROL".
- (5) Perform "A/F CONTROL" when idle condition (press the \leftarrow or \rightarrow button).

Result:

A/F sensor reacts in synchronizing with increase and decrease of injection volume (+25 % \rightarrow rich output: Less than 3.0 V, -12.5 % \rightarrow lean output: More than 3.35 V) Heated oxygen sensor reacts in synchronizing with increase and decrease of injection volume (+25 % \rightarrow rich output: More than 0.55 V, -12.5 % \rightarrow lean output: Less than 0.4 V)

NOTICE:

However, there is a few second delay in the A/F sensor output. And there is about 20 seconds delay in the heated oxygen sensor.

DIAGNOSTICS - ENGINE (5VZ-FE)

	Output voltage of A/F sensor (sensor 1)	Output voltage of heated oxygen sensor (sensor 2)	Mainly suspect trouble area
Case 1	Injection volume +25 % -12.5 % Output voltage More than 3.35 V Less than 3.0 V	Injection volume +25 % -12.5 % Output voltage More than 0.55 V Less than 0.4 V	
Case 2	Injection volume +25 % -12.5 % Output voltage No reaction	Injection volume +25 % -12.5 % Output voltage More than 0.55 V Less than 0.4 V	A/F sensor (A/F sensor, heater, A/F sensor circuit)
Case 3	Injection volume +25 % -12.5 % Output voltage More than 3.35 V Less than 3.0 V	Injection volume +25 % -12.5 % Output voltage No reaction	Heated oxygen sensor (heated oxygen sensor, heater, heated oxygen sensor circuit)
Case 4	Injection volume +25 % -12.5 % Output voltage No reaction NG	Injection volume +25 % -12.5 % Output voltage No reaction	Extremely rich or lean of the actual air–fuel ratio (Injector, fuel pressure, gas leakage in exhaust system, etc)

The following procedure of A/F CONTROL enable that to check its output (show its graph indication) of A/F sensor and heated oxygen sensor.


To display the graph indication. Select and push the "YES or NO" button 2 data "AFS B1S1 and O2S B1S2" or "AFS B2S1 and O2S B2S2" and press button "4" after selecting "ACTIVE TEST/ A/F CONTROL/USER DATA".

HINT:

- The A/F sensor signal must be checked using the hand-held tester or the OBD II scan tool.
- DTC P2A00 may be also detected, when the air fuel ratio is stuck rich or lean.
- A low A/F sensor voltage could be caused by a rich air fuel mixture. Check for conditions that would cause the engine to run rich.
- A high A/F sensor voltage could be caused by a lean air fuel mixture. Check for conditions that would cause the engine to run lean.
- Read freeze frame data using the hand-held tester or the OBD II scan tool, as freeze frame records the engine conditions when a malfunction is detected. When troubleshooting, it is useful for determining whether the vehicle was running or stopped, the engine was warmed up or not, the air-fuel ratio was lean or rich, etc. at the time of the malfunction.

1

Are there any other codes (besides DTC P2A00) being output?



NO

2 Connect OBDII scan tool or hand-held tester, and read value for voltage output of A/F sensor.

PREPARATION:

- (a) Connect the hand-held tester or the OBD II scan tool to the DLC 3.
- (b) Warm up the A/F sensor (bank 1 sensor 1) with the engine at 2,500 rpm for approximately 90 seconds.
- (c) Read A/F sensor voltage on the OBD II scan tool or hand-held tester.

CHECK:

- Hand-held tester only: Select the "DIAGNOSIS/ENHANCED OBD II/SNAPSHOT/MANUAL SNAPSHOT/USER DATA" mode on the hand-held tester.
- (b) Select "AFS B1 S1/ENGINE SPD" and press button "YES".
- (c) Monitor the A/F sensor voltage carefully.
- (d) Check the A/F sensor voltage under the condition as follows.
 - (1) Allow engine to idle for 30 seconds.
 - (2) Engine is racing at approx. 2,500 rpm (when engine revolution is not suddenly changed).
 - (3) Raise the engine speed to 4,000 rpm and release the accelerator pedal fully closed quickly.

<u> 0K:</u>


Standard:

Condition (1) and (2)

Voltage change a little in the vicinity of $3.3 \text{ V} (0.66 \text{ V})^*$ (between approx. 3.1 - 3.5 V) as shown in the illustration.

Condition (3)

A/F ratio sensor voltage increase to 3.8 V (0.76 V)* or more during engine deceleration (when fuel cut) as shown in the illustration.




HINT:

- Whenever the output voltage of the A/F sensor remains at approx. 3.3 V (0.660 V)* (see dwg. 2) under any conditions as well as the above conditions, the A/F sensor may have an open-circuit. (This will happen also when the A/F sensor heater has an open-circuit.)
- Whenever the output voltage of the A/F sensor remains at a certain value of approx. 3.8 V (0.76 V)* or more, or 2.8 V (0.56 V)* or less (see dwg. 2) under any conditions as well as the above conditions, the A/F sensor may have a short–circuit.
- The ECM will stop fuel injection (fuel cut) during engine deceleration. This will cause a lean condition and should result in a momentary increase in A/F ratio sensor voltage.
- The ECM must establish a closed throttle position learned value to perform fuel cut. If the battery terminal has been disconnected, the vehicle must be driven over 10 mph to allow the ECM to relearn the closed throttle position.
- When the vehicle is driven: In the case that the output voltage of the A/F sensor is below 2.8 V (0.76 V)* during fuel enrichment (for example, when the vehicle tries to overtake another vehicle on a highway, the vehicle speed is suddenly increased with the accelerator pedal fully depressed), the A/F sensor are functioning normally.
- The A/F sensor is a current output element, and therefore the current is converted into voltage inside the ECM. If measuring voltage at connectors of A/F ratio sensor or ECM, you can obtain a constant voltage.
- *: When using the OBD II scan tool (excluding hand-held tester).



N	IG
	/

3 Check resistance of A/F sensor heater.



PREPARATION:

Disconnect the sensor connector.

CHECK:

NG

Using an ohmmeter, measure the resistance between terminals +B and HT.


<u>OK:</u>

at 20°C (68°F)	0.8 – 1.4 Ω
at 800°C (1,472°F)	1.8 – 3.2 Ω
	· · · · · · · · · · · · · · · · · · ·

OK

4

Check EFI main relay (Marking : EFI).



PREPARATION:

Remove the EFI main relay from RB No. 2.

Replace A/F sensor.

CHECK:


Inspect the EFI main relay.


<u>OK:</u>

Condition	Tester connection	Specified condition
•	1 – 2	Continuity
Constant	3 – 5	No continuity
Apply B+ between terminals 1 and 2.	3 – 5	Continuity
NG Replace EFI main relay		

οκ

5	Check for open and short in harness and connector between ECM and A/F sensor (See page IN–28).	
	NG Repair or replace harness or connector.	
ОК		





16	Perform confirmation driving pattern (See page DI-421).
GO	
17	Is there DTC P2A00 being output again?



Check and replace ECM (See page IN–28) and perform confirmation driving pattern (See page DI–421).

NO	
18	Did vehicle run out of fuel in past?
	NO Check for intermittent problems (See page DI–218).
YES	
DTC P2A00 is caused by shortage of fuel.	