CO/HC INSPECTION


EM03L-09

HINT:

This check is used only to determine whether or not the idle CO/HC complies with regulations.

1. INITIAL CONDITIONS

- (a) Engine at normal operating temperature.
- (b) Air cleaner installed.
- (c) All pipes and hoses of air induction system connected.
- (d) All accessories switched OFF.
- (e) All vacuum lines properly connected.
- (f) SFI system wiring connectors fully plugged.
- (g) Ignition timing checked correctly.
- (h) Transmission in neutral position.
- (i) Tachometer and CO/HC meter calibrated by hand.
- 2. START ENGINE
- 3. RACE ENGINE AT 2,500 RPM FOR APPROX. 180 SE-CONDS



- 4. INSERT CO/HC METER TESTING PROBE AT LEAST 40 cm (1.3 ft) INTO TAILPIPE DURING IDLING
- 5. IMMEDIATELY CHECK CO/HC CONCENTRATION AT IDLE AND/OR 2,500 RPM

Complete the measuring within 3 minutes.

HINT:

When doing the 2 mode (2,500 rpm and idle) test, follow the measurement order prescribed by the applicable local regulations.

6. TROUBLESHOOTING

If the CO/HC concentration does not comply with regulations, troubleshoot in the order given below.

- Check the A/F sensor or heated oxygen sensor operation (See page DI-288).
- (2) See the table below for possible causes, and then inspect and correct the applicable causes if necessary.

2003 TOYOTA TACOMA (RM1002U)

Author: Date: 1177

ENGINE MECHANICAL (5VZ-FE) - CO/HC

CO	HC	Symptoms	Causes
Normal	High	Rough idle	5. Faulty ignition: • Incorrect timing • Incorrect timing
			Fouled, shorted or improperly gapped plugs
			Open or crossed high-tension cords
			6. Incorrect valve clearance
			7. Leaky intake and exhaust valves
			8. Leaky cylinder
Low	High	Rough idle	1. Vacuum leak:
		(Fluctuating HC reading)	• PCV hose
			Intake manifold
			Air intake chamber
			Intake air connector
			• Throttle body
			• IAC valve
			Brake booster line
			2. Lean mixture causing misfire
High	High	Rough idle	Restricted air filter
		(Black smoke from exhaust)	2. Plugged PCV valve
			3. Faulty SFI systems:
			Faulty fuel pressure regulator
			Clogged fuel return line
			Defective ECT sensor
			• Faulty ECM
			Faulty injector
			Faulty throttle position sensor
			Faulty MAF meter

Author: Date: 1178